




BEFORE
CLEAN



AFTER
CLEAN



Low Fouling Pack Facilitates Easier Pack Cleaning at Food Factory

TC Engineering Services Case Study

**TC Engineering
Services**

VAT Regn No:- 164 2676 95

Phone/Fax Office: 01925 711862

Contact:-

Tim Cuthbert: 07771 984726

E-mail:

timhpcc@aol.com

tim@tcengineeringservices.co.uk

Web:

www.tcengineeringservices.co.uk

A food factory in the Midlands were having major problems with grease and food depositing in the packing in their cooling tower. This was extremely difficult to remove during a clean.

TC Engineering Services recommended new Low-Fouling packing that could be cleaned easier when removed.

The results of this work showed that not only did the pack have less deposition, it was much easier to clean due to its open design (i.e. it can be cleaned from all sides).

Client also perceived no drop in cooling performance